


Pin	Colour	Function*
1	white	Encoder A
2	white/black	Encoder /A
3	red	Encoder B
4	red/black	Encoder /B
5	yellow	+5V DC out
6	yellow/black	Do Not Use
7	green	WDOG+
8	green/black	WDOG
9	blue	IN A
10	blue/white	IN Common
11	brown	Encoder Z
12	brown/white	Encoder /Z
13	orange	NC
14	orange/black	NC
15	grey	0V Encoder
16	grey/black	Do Not Use
17	violet	Vout +
18	violet/white	Vout
19	pink	Do Not Use
20	pink/black	IN B

* Function dependant on Axis Type.



QUICK START GUIDE MDR CABLE

Strip the non connector end of the cable to form flying leads and wire as required



UK | USA | CHINA | INDIA
WWW.TRIOMOTION.COM
THE MOTION SPECIALIST

CAD data Drawings to aid packaging and mounting are available in various formats from the Trio web site. Products should be wired by qualified persons.
Specifications may change without notice. E & OE

Quick Start v1 December 2016